Date	Location	Description	Action Taken	Date Complete	
		Path of travel from the side door to the main office is un even and			
2.26.2016	M&O	considered a trip hazard	None at this time		
212012010					
		Corp Yard entrance from parking lot	Will be resolved as part of		
2.26.2016	Corp Yard	7 needs remedy	the 2016 Asphalt Project		
	Between Parking Lot 1 and	Trip Hazrd: Conform asphalt and	Will be resolved as part of		
2.26.2016	e e e e e e e e e e e e e e e e e e e	add parking blocks	the 2016 Asphalt Project		
		Smooth out walking path between	Will be resolved as part of		
2.26.2016	1 and corp yard	lot 1 and corp yard	the 2016 Asphalt Project		
2.26.2016	Between Paring lot 1 and M&O	Upgrade Well Equpiment?	Resolve with Scott & Chris		
		Reconcile lighting fixtures/old	Part of lighting project spring		
2.26.2016	Campus Wide	mounts, etc.	2016		
		This because in combands due to the	Mill be used as next of		
2 26 2016	Parking Lot 7	Trip hazards in asphault due to tree roots and age of asphalt	Will be resolved as part of the 2016 Asphalt Project		
212012010			PG&E will cap and remove		
2.26.2016	Between parking lot 1 and 6	PG&E bunker removal	obsolete pipes		
	Constant ADA and the		ANTILLE CONTRACTOR OF A DESCRIPTION		
2 26 2016	Crosswalk near ADA parking in lot 6 near pathway	confer electrical box	Will be resolved as part of the 2016 Asphalt Project		
2.20.2010	in lot o hear pathway	paint tread on four sets of stairs and			
2.26.2016	PA Building facing circle drive		no. 7006		
2 26 2016	PA Building: Drive way by band room and design shop	uneven concrete			
2.20.2010	LRC frontage road between				
	Parking lot 5 and center of				
2.26.2016	campus	alligatored concrete			

	Exterior LRC between TV	Light fixture cover has become	Submitted as Work Order
2 26 2016	studio and Parking lot 5	detached and could fall	no. 7008
2.20.2010			10.7000
2 26 2016	Perimeter of Student Services	Heavy agregate concrete	
2.20.2010	Student services exterior 2nd		
2 26 2016	floor near bunker	lower cover to eliminate trip hazard	
2.20.2010		lower cover to emmate the hazard	Submitted as Work Order
2 26 2016	Perimeter of Student Services	Paint tread nosings on all stairs	no. 7009
2.20.2010	refineter of student services	Need to remove temporary fencing	
		and come up with permanent plan	
	Student services exterior 2nd	to block access to the roof of the	Submitted as Work Order
2 26 2016	floor near bunker	bunker	no. 7010
2.20.2010	Between student Services	Remove and replace splintered	Submitted as Work Order
2.26.2016		wooden benches	no. 7011
2.20.2010		wooden benenes	
	retaining wall in the student	put a cover over exposed electrical	Submitted as Work Order
2.26.2016	services court yard (by grass)	box	no. 7012
2.20.2010	Sunken Circle outside		Submitted as Work Order
2.26.2016	Fusselman Hall	Repair steps in sunken circle	no. 7013
	LRC Exterior facing AC	Remedy the "exit to nowhere"	
	Exterior stairs between LRC		Submitted as Work Order
2.26.2016		Chipped nosing/stairs	no. 7018
	Exterior stairs between LRC	Missing Handrail and handrailing	Submitted as Work Order
2.26.2016		end caps missing	no. 7014
		vent protruding from the brick wall	
	Exterior stairs between LRC	at the top of the stairs on the left is	Submitted as Work Order
2.26.2016	and AC	facing into campus	no. 7015
			Plants have been placed to
			block the hazard. Need
			Permanent solution.
		Trip hazards at benches in LRC	Submitted as Work Order
2.26.2016	AC	entrance to the building	no. 7016
		Remove Motorcycle Parking sign at	Submitted as Work Order
2.26.2016	Health Center	the rear of the building	no. 7017

IVC CAMPUS

IVC CAIVIP	IVC CAMPUS				
		Pathway between buldings 10 & 11 is crumbling and needs to be			
		conformed where it meets decking			
3.7.2016	Administrative Cluster	infront of building 10			
5.7.2010	Authinistrative Cluster	Puddling around the doors due to			
3.7.2016	Building 12	low points in the concrete			
5.7.2010	Saurani 8 12	Walkway leading to bridge has a trip			
		hazard, concrete should be			
3.7.2016	Building 17	conformed to level of the bridge.			
		Pathways leading around the cluster			
		and toward the pool are badly			
3.7.2016	Ohlone Cluster	cracked and crumbling			
		Fencing along the creek is			
		deteriorating and bolts are sticking			
3.7.2016	Ohlone cluster	out of what remains of the fence			
2 7 2010	Deal	ramp leading from the parking lot to			
3.7.2016	Pool	the pool has a craked utility cover			
		Cap for light post leaving from pathway to the pool needs a cap			
		placed over the access to the	Submitted as Work Order		
3.7.2016	pool	electrical components	No. 7019		
5.7.2010		life rings were observed to be aged			
3.7.2016	pool	and possibly cracking			
		Nosing of two stair cases need	Submitted as Work Order		
3.7.2016	pool	painting	no. 7020		
		fencing along the pathway to the far			
3.7.2016	tennis courts	tennis court has falled fancing			
		nosing on stairs for both tennis	Submitted as Work Order no		
3.7.2016	tennis courts	courts need paiting	7021		

3.7.20)16 Park	king lot 6 (IVC)	Remove "Van Accessible from second ADA space	Submitted as Work Order no. 7022
3.7.20)16 Park	king lot 6 (IVC)	ADA spaces are not compliant	Submitted as Work Order no. 7023
			Parking lot needs to be conformed, very uneven and causing water to	Will be resolved as part of
3.7.20)16 Park	king lot 6 (IVC)	pool	the 2016 Asphalt Project Wood will be
			failed retaining wall between parking lot 5 & 6 and being held up	removed/pushed back to aleviate pressure on the light pole. Submitted as Work
3.7.20)16 Fror	ntage road (IVC)	by a light pole	Order 7024
3.7.20)16 Park	king lot 5 (IVC)	Lower section: broken fence near creek	
3.7.20)16 Park	king lot 4 (IVC)	ADA spaces are not compliant	
3.7.20)16 Buil	ding 11	Police Parking pad is eroding into the creek, the fence is also broken	
3.7.20		ninistrative Cluster	Metal pieces sticking out of flower bed. They once held boards and acted as benches.	Submitted as Work Order 7025
5.7.20	Aun		deted as benches.	1025